

Tug "TAYWOOD TID"

A representative of Messrs. Taylor Woodrow Limited visited this office stating that it was not proposed to have the bottom plating coated. He was informed that this would involve a special annual examination of this part of the ship and a qualification of class being made in this respect.

It is understood that the fitting of a new generator has involved certain alterations and it was arranged that he would communicate in writing on this subject.

*R.A.P.*

15th March, 1950



© 2021

Lloyd's Register

011646-011656-0374