



Aftwards examined under steam and safety valves adjusted to 140 lb/sq  
Oil fuel burning installation and steam smothering gear, pipes, tanks, valves.  
Cabin gear etc. examined and found satisfactory

Pumping arrangements valves, pipes, strainers etc opened up and examined.  
Main and auxiliary machinery tried under working conditions and found  
satisfactory.

Repairs:- several minor repairs effected at this time

Note/ No opportunity was given at this time to verify the spare gear. Should  
to had been completed and placed on board by the repairs.

Date of writing  
No. in Su  
Reg. Book  
3268 on  
Built at  
Engines ma  
Boilers ma  
Registered  
Nom. Horse  
Trade for wh

ENGINES,  
Dia. of Cylind  
Crank shaft, d  
Intermediate S  
Tube Shafts, c

Bronze Liners,  
propeller boss  
If the liner doe  
If two liners an  
at 7/8

Propeller, dia.  
Feed Pumps u  
Bilge Pumps u  
Feed } No. a  
Pumps } How o

Ballast Pumps,  
Are two indepe  
Bilge Pumps:  
In Pump Ro

Main Water Ci  
No. and size  
Are the Bilge S  
Are all Sea Co  
Are they fixed s  
Are they each f  
What Pipes pa  
What pipes pa  
Are all Pipes, c  
Is the arrangem  
compartment to

MAIN BOIL  
Which Boilers  
No. and Descr  
IS A REPC  
IS A DON  
Can the donkey  
PLANS. A

Superheaters  
Has the spare g  
State the princ

The f