

Received from Chief Ship Surveyor.....119 SEP 1957

SHIP'S NAME....."AFRICAN BARON".....REPORT.....Emd. No. 162.

Standing Conditions of Class: NONE

Endorsement of Certificate (~~As before~~ None)

Area of Present Survey: (Afloat and in dry dock)

Docking. Repairs on account of damage caused by striking submerged object.

Recommendation:

SUBMITTED record "DS 7,57" be assigned SUBJECT to welded doublers at upper deck hatch corners No.2 (p & s.f.) and No.4 (p & s.a.) and (p.s.f.) being specially examined at next drydocking and to set in shell plates A.20 & 21 (s.s.a.) etc. being dealt with as necessary by next Special Survey, with Endorsement of Certificate.

DS 7,57. Subject.

ENDORSEMENT OF CERTIFICATE.

Bottom plating wavy and bilge plating (p & s) pitted to to be kept under observation and reported upon each drydocking. Indents in shell plates (s.s.f.). INSERT IN R.B.:- N.S.

OFFICE NOTE:

Bottom stiffened - Gls. 4,59.

C.S.S. Records Dept.
to note.

C.S.S. Records Dept.
to note.



1520-596110-656110