

114 JAN 1959

Received from Chief Ship Surveyor.....

SHIP NAME "CITY OF CARLISLE" REPORT Nwc. No. 115776

GB

Standing Conditions of Class: Subject to shell plate riveting in way of O.T. bunker tanks (p & s amids) being specially examined and dealt with as necessary at the Special Survey.

Re-issuance of Certificate (As before ~~or None~~)

Surveys due: SPECIAL SURVEY (C) became due 3,58. Special Survey commenced Bal. 3,58. Proposal to postpone completion of this survey until 3,59 previously approved.

Area of Present Survey: (Afloat and in dry dock)

Completion of Special Survey: Permanent repairs to damages from various causes, including the conditions of class and part S.R.L. Appendix items.

Special Features: Thrust block seating completely re-built in accordance with approved plan.

Interim Certificate in order (Yes-~~No~~-None)

Claims Outstanding: (If any for S.S.)

NONE.

Work completed by

Recommendation: SUBMITTED record of 'DS 11,58' and Notation of 'SS Shl. 11,58' be assigned as recommended, but without special conditions.

DS 11,58
SS Shl. 11,58 Without.

S.R.L. APPENDIX NOTE (AMENDED).

Windlass clutch hinge pin repaired by Metalock.

Handwritten: CBM 18.12.58



© 2021

Lloyd's Register Foundation