

29 MAY 1957

23 MAY 1957

Rpt. 9

Date of writing report 10/5/1957

Received London

Port of GENOA

No. 22347

Survey held at Genoa

No. of visits 2

First date 30/4/57

Last date 8/5/57

## REPORT OF PERIODICAL SURVEYS & REPAIRS OF MACHINERY

No. in R.B. 91476 S.S. "LAGOS MICHIGAN"

Gross tons 7060 Date of build 1944

Owners Cia. Armadora S. Francisco SpA Managers

Port of Registry Panama

Engines made 1944 By John Inglis Co. Ltd.

Type T 3 Cy.

No. of Main Engines 1 No. of Screws 1

Records of Survey & Special Notations as per Register Book

No. of Main Boilers 2 W.P. 250 lbs

No. of Aux./Donkey Boilers - W.P. -

Surveyed Afloat or in Dry Dock afloat

Nature of Survey Boiler repairs

Was Damage Report issued? - Int. Cert.? yes

Last Report (For Head Office only)

2600 KRH

Hull	Machinery
+100 A1	+ LMC 9/54
SS 6/55	BS M 12/56
Dkg 5/56	TS CL 9/54 N
	SP 6/55

The condition of any of the following items is to be described as "good" only when the part has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the due date of the next Periodical Examination a distinguishing mark thus † should be inserted against the item and the circumstances and action recommended described fully under "defects and repairs". At part or complete Special Surveys those items which are not applicable to the ship should be cancelled with a black line; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

DOCKING Propellers Wear Down of Stern Bushes Oil Glands Sea Connections

Fastenings Has Screwshaft Tubeshaft been drawn? Date of Examination Has Shaft been changed?

Has Shaft now fitted been previously used? Has Shaft now examined/fitted a continuous liner? Approved oil gland?

MAIN ENGINES (Recip. Steam or I.C.) PORT STARBOARD

1 Cyls., Covers, Pistons & Rods

2 Valves & Gears

3 Connecting Rods, Top Ends & Guides Side Centre

4 Crankpins & Bearings Side Centre

5 Journals & Bearings

### MAIN ENGINE DRIVEN AIR COMPRESSORS

6 Cyls., Covers, Pistons & Rods

7 Connecting Rods & Top Ends

8 Crankpins & Bearings

9 Journals & Bearings

10 Coolers & Safety Devices

### MAIN ENGINE DRIVEN SCAVENGE PUMPS

11 Cyls., Covers, Pistons & Rods

12 Connecting Rods & Top Ends

13 Crankpins & Bearings

14 Journals & Bearings

15 Levers

16 SCAVENGE BLOWERS

17 SUPERCHARGERS

### MAIN TURBINES

18 Casings, Rotors, Blading, Bearings & Thrusts

19 EXHAUST STEAM TURBINES (WITH RECIP. ENGINES)

20 STEAM COMPRESSORS

21 CLUTCHES & HYDRAULIC COUPLINGS

22 REDUCTION GEARING

23 THRUST BLOCKS, SHAFTS & BEARINGS

24 INTERMEDIATE SHAFTS & BEARINGS

25 HOLDING DOWN BOLTS & CHOCKS

26 CONDENSERS (MAIN & AUX.)

27 STEAM RE-HEATERS

28 DE-SUPERHEATERS

29 STOP & MANOEUVRING VALVES

30 MAIN ENGINE DRIVEN PUMPS

31 CRANKCASE DOORS & EXPLOSION RELIEF DEVICES

Have Main Engines been tested working and manoeuvring?

OPINION OF MACHINERY AND RECOMMENDATIONS The machinery of this vessel, as now seen, is eligible in my opinion, to remain as classed without fresh record of survey and without condition in respect of 4" tubes in starboard boiler.

Date of Committee

THURSDAY - 6 JUN 1957

Decision

As now, without spe. edn.



32 Essential Independent Pumps (Identify by position)
33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls
34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?
35 Fresh Water Coolers
36 Lub. Oil Coolers
37 Heaters (state service)
38 Independent Air Compressors, Coolers & Safety Devices
39 Air Receivers & Safety devices—Main
40 Auxiliary
41 Oil Fuel Tanks (Not forming part of hull structure)
42 Evaporators
43 Have Evaporator Safety Valves been tested under steam?
44 Steering Machinery
45 Windlass
46 Fire Extinguishing Arrangements
AUXILIARY ENGINES (Identify by position)

PROPULSION		ELECTRICAL EQUIPMENT	
		PORT	STARBOARD
a	Generators		
b	Exciters		
c	Air Coolers		
d	Motors		
e	Air Coolers		
f	Control Gear, Cables, etc.		
g	Insulation Resistance		
h	Insulating Oil Test		
i	Overspeed Governors		
j	Magnetic Couplings		
k	Air Gap		
		AUXILIARY EQUIPMENT	
		l Generators & Governors	
		m Motors	
		n Switchboards & Fittings	
		o Circuit Breakers	
		p Cables	
		q Insulation Resistance	
		r Steering Gear Generators and Motors	
		s Navigation Light Indicators	

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)
MAIN
AUXILIARY, DONKEY or PRESS
Superheaters
Safety Valves
Mountings, Doors & Fastenings
Safety Valves Adjusted to: Sat. Spt.
Boiler Securing Arrangements
Main Economisers
Exhaust Gas Heated Economisers
Steam Heated Steam Generators
Steam Generator Safety Valves Adjusted to
Were Oil Burning System & Remote Controls examined working in accordance with Rules?
Forced Circulating Pumps
Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules?
Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)
Main
Auxiliary (over 3 in. bore)
Were Copper Pipes annealed?
Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

CONDITION OF CLASS. Bottom row of 4" tubes in starboard boiler being re-examined not later than July 1957.

The lower row of 4" tubes in the starboard boiler, now renewed. The boiler examined under hydraulic test on completion of repairs and all found satisfactory. This condition of class may now be deleted.

LEAVE THIS SPACE BLANK

Survey fees

Rhm. Lt. 16,000
Damage fee Lt. 1,330
C.A.M. FUND Lt. 3,000
Expenses... Lt. 618
REV. TMR. Lt.

Date when A/c rendered

10/1/57

© 2021

Lloyd's Register Foundation