


LLOYD'S REGISTER OF SHIPPING


UNITED WITH THE BRITISH CORPORATION REGISTER

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name S.S. "PHAEAX II" Official No. 1730Port of Registry PanamaThis ship has been under survey at Vancouver, B. C.on 13th February, 1954 and the following alterations to the conditions of assignment of loadlines have now been effected/~~found~~:—

MIDSHIP DECK HOUSE:- Access door to Steward's Store in 'tween deck starboard side now part plated over and a new steel water tight door fitted, new opening 22-1/2" x 4' 10", sill 20", door 1/4" thick with 6 toggles operated both sides.


SURVEYOR TO LLOYD'S REGISTER OF SHIPPING
VANCOUVER, B.C.



© 2021

Lloyd's Register
Foundation

011805-011812-0226

37566

9 - MAR 1954