

Class is subject to

the main engine exhaust butterfly valves and actuating gear being repaired and dealt with as necessary at Santos D which port the ship is now proceeding

4E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor..... 21 AUG 1962

SHIP'S NAME

JOZEF CONRAD

REPORT


SAN.

No. 3320

SRL The Surveyor reports all main engine exhaust valve assemblies examined, overhauled and repaired or renewed where necessary and he recommends that item be renewed from the list

It is submitted that this vessel is eligible to remain as CLASSED.

Without subject



© 2021

Lloyd's Register  
Foundation

011823-011825-0010

27/8/62