

Rpt. 8

REPORT OF SHIP SURVEYS AND REPAIRS

Received London

Ship's Name SS/MS "UNION FAIR" Gross tons 6970
Is there a rpt. 9? Yes Port Yokohama Rpt. No. 5316
No. of visits 5 First date 28-5-64 Last date 1-6-64
Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? - Last rpt. (H.Q. only) ~~Yes~~ M402
Date of completing rpt. 6-6-64 Surveyed at, if different from Port above Tokyo
Surveyed afloat and/or in D.D. Both Last date of examination in D.D. 30-5-64
Has a Load Line Survey been held? Yes Freeboard Marks verified Yes

State which additional Rpt. 8 is attached: (Com); (PS); (DR); (EQ); (Rig)

Survey fees

DS ¥ 10,500.-

GE ¥ 67,900.-

Damage fee -

Expenses

¥ 2,000.-

S.A. fee ¥ 8,000.- (HT)

I have surveyed the above ship in accordance with the Rules for Periodical Load Line Survey, Docking Survey and General Examination for Postponement of Special Survey until March 1965.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

W. & T. Repairs:

2 air pipes (above deck) renewed.

GENERAL EXAMINATION FOR POSTPONEMENT OF SPECIAL SURVEY UNTIL MARCH 1965:

In view of satisfactory nature of general examination and survey now held, it is submitted that the Owner's request for postponement of Special Survey until March 1965, warrants favourable consideration of the Committee.

I recommend that this ship remain as classed with/without fresh record of dry docking 5/64 subject to any outstanding conditions of class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

TUESDAY 28 JUL 1964

kn

12.63 KOB

write X/A (PP+M)

Deferred for SS.

DS 5.64

MBS 2.64

Postponement of SS
until 3.65 approved

B.R. MAC LEENAN

Surveyor to Lloyd's Register of Shipping

H. TERASHIMA

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

011823-011825-0149 1/2

Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name SS/~~MS~~

"UNION FAIR"

SS. (C) Due 3/64

Port

Yokohama

Rpt. No. 5316


<u>Examined & condition</u>		<u>Examined & condition</u>	
In dry dock from	28-5-64	* Air & sounding pipes	good
" " " to	30-5-64	Doublers under " "	good
Shell plating	good	Steering arrangements (main)	good
Sternframe	good	" " (aux)	good
Rudder	good	Windlass	good
Was rudder lifted?	no	Masts & rigging	good
Plating, etc. in way of shell openings	not exd.	Hand pumps & suction	not exd.
Side scuttles & deadlights	good	W.T. doors	good
Overbd. scuppers & discharges	good	Bulwarks, freeing ports, etc.	good
F.P. spaces	good	Summer freeboard as verified	11'-5" ✓
Chain locker	not exd.		
A.P. spaces	good		
Engine space	good		
Boiler space	good		
Under E. & B.	good		
Coal bunker	none		
Tunnel & well	good		
Cement, asphalt, etc., on btm. shell	good		
Weather decks	good		
* Casings	good		
* Deckhouses	good		
* Superstructures	good		
* Skylights	good		
* Companionways	good		
* Hatchways	good		
* Ventilators	good		
Other items:	-		

EQUIPMENT:

Equipment letter	a +
Fee ltr., if diff. from eqpt. ltr.	-
Anchors: No. on board	3B
State if ranged	no
Length on board	stated complete
Mean dias. range from	- to -
Rule length	- Dia. -
Mooring ropes	sufficient

* These items to include their closing appliances
Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"

kn



B.R. MAC LENNAN & H. TERASHIMA
Surveyor to Lloyd's Register of Shipping

Lloyd's Register
Foundation
011823-011825-0149^{2/2}

HOLDS & 'TWEEN DECKS:		Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold	good	F.P. tank	good	-
"	'Tween decks	good	A.P. tank	good -	-
			D.B. tanks & c/dams		
			No.3) No.5) (part) No.7)	good	-
No. 2	Hold	good			
"	'Tween decks	good			
No. 3	Hold	good	O.F. bunkers	-	-
"	'Tween decks	good			
			Settling tanks	-	-
No. 4	Hold	good			
"	'Tween decks	good			
			Deep tanks	-	-
No. 5	Hold	good			
"	'Tween decks	good	Side tanks	-	-
No. 6	Hold	-	Wing tanks	-	-
"	'Tween decks	-			
			Other tanks:	-	-
	Cargo battens	good			
	Ceiling, etc.	good			



© 2021

Lloyd's Register
Foundation

175/1228