

Received from Chief Ship Surveyor **28 SEP 1954**

SHIP'S NAME "STAD HAARLEM" REPORT Rot. No. 38158

Standing Conditions of Class:

Subject to cargo battens being placed in order at the first opportunity, and to deep tanks forward not being used as such until they are dealt with, and to permanent repairs to bottom plating in way of No.5 hold bilge well aft by next drydocking.

ACTION is DEFERRED for Special Survey.  
 Endorsement of Class (B) (As before ~~xxxxxx~~)

Surveys due: SPECIAL SURVEY (B) due 12,53.

Place of Present Survey: (Afloat and in dry dock)

Docking: Special Survey: Conversion for oil fuel burning:  
 Equipment (bower anchor renewed):

Damage repairs to the deferred and Endorsement (B) items as above -  
 cause not stated.

Special Features: All cargo battens have been removed.

Interim Certificate in order (Yes-No-None)

Conditions Outstanding: (If any for S.S. or A.S.)

to be completed by:

Recommendation:

SUBMITTED record of docking 7,54 and Notation of 'ss.Rot. 7,54' be assigned, but without special conditions.

7,54 Rot. )  
 ss. Rot. 7,54. ) Without.

~~DELETE 'ENDORSEMENT OF CLASS (B)'~~

INSERT IN R.B.

"Fitted for oil fuel 7,54 F.R. above 150°F"

MT O.F.

Cargo Battens Not Fitted.

OFFICE NOTE:- N.S. 13.7.54.

The Certificate of Classification to be endorsed "Cargo Battens not fitted" and the same notation to be printed in the Register Book.



© 2021 Lloyd's Register Foundation  
 21-9-54.  
 01823-01825-0154