

COPY.

24 SEP 1946

Lloyd's Register of Shipping.

Port

BOMBAY.

2nd AUGUST 1946

This is to Certify that I have

surveyed the Steel Screw Steamer "EMPIRE HANDURAS" 7320 tons gross
Sunderland, as she lay in Hughes Drydock, Bombay

for


CONDITION

I have transmitted to the Committee of Lloyd's
Shipping, London, a Report, stating that all repairs
recommended by me have been completed to my satisfaction, and

I have Recommended that she be continued in her present
condition with fresh record of Survey 7.46, subject to pitting and
corrosion on shell plates on starboard and port sides from
of bilge up to 11'-6" mark on starboard side for whole length,
port side mainly on after half length and on isolated places
bottom being specially examined at next drydocking, also pitted
points in way of affected side plating. Indented shell plate
from ford.(s.s.) in 1st below sheer,
is not fit to carry dry and perishable cargo.

John Rundle
Surveyor to Lloyd's Register.

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-
The Committees of the Society use their best endeavours to ensure that the functions of the Society are
performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any
liability whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its
Members in any entry in the Register Book or other publication of the Society, or for any error of judgment,
negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of



© 2021

Lloyd's Register
Foundation

011823-011825-0168