

/ID

LLOYD'S REGISTER OF SHIPPING

St. Kongensgade 49¹, Copenhagen, K.

Telegrams: Engineer, Copenhagen

Telephone: Minerva 4015*

8th November, 1960

be addressed
ORS,
Shipping,
K.

S. The Secretary,
London.

Dear Sir,

RECEIVED

11 0 NOV 1960

m.s. "VÖLKERFREUNDSCHAFT"

With reference to your Classn.S. letter dated 4th inst., we have to state that the sole piece and lower part of sternframe were carefully examined as stated in the damage report page 3 "heel piece to be carefully examined" and found satisfactory. Only a small scratch on the after end of the casting was noted and smoothed off. Regarding the lower part of the sternframe, we may add that the aftermost keel plate was badly damaged (buckled and fractured) and now renewed. The buckling was forward of the above cast heel piece.

The lower part of the rudder repaired as stated in our damage report.

Yours faithfully,

M. J. Christensen

SURVEYOR TO LLOYD'S
REGISTER OF SHIPPING



© 2021

Lloyd's Register
Foundation

011834 - 011843 - 0133

SR

CLASSIFICATION

SR

CLASSIFICATION

H

mm

11.11.60

Submitted
damage repairs
be forwarded to DSRK
(See Encl. dated 3.11.60.

LOUIS LOUISIANA

LOUISIANA LOUISIANA

LOUISIANA LOUISIANA

LOUISIANA LOUISIANA

LOUISIANA LOUISIANA

LOUISIANA LOUISIANA



© 2021

Lloyd's Register
Foundation

LOUISIANA LOUISIANA

LOUISIANA LOUISIANA

LOUISIANA LOUISIANA

LOUISIANA

LOUISIANA LOUISIANA

LOUISIANA LOUISIANA

LOUISIANA LOUISIANA