

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

19th July, 1963

Dear Sirs,

CLASSING LETTER

C
DHGK/RW

11576 "SAGA MARU". As recommended. You should state whether main fuel-valve cooling pumps and cooler are fitted, and if so whether they have been examined during the present C.S. cycle.

11568 "HULDA MAERSK". As recommended, except that the notation A.B.S. 3.63 has not been assigned at this time, as the exhaust gas boiler safety valves still require to be adjusted. You should, therefore, issue an amended Interim Certificate, and forward a copy to this Office.

11663 "SHOSEI MARU". As recommended, except that the notation A.B.S. 4.63 has been assigned, and it is considered that the main engine No. 2 piston crown should be re-examined by the end of May, 1964. You should, therefore, issue an amended Interim Certificate, and forward a copy to this Office.

Yours faithfully,

pro Clerk to the
Classification Committee

The Surveyors,
Kobe



© 2021

Lloyd's Register
Foundation

011844-41850-0718