

Inspected by Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

VESSEL'S NAME

Accruity

Rpt.

*Gr.**No. 5-6264**Gr.**No. 20030**Lon.**" 101991**Met.**" 8036*

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Type of Engine

Pei Engines 2 SC SA.
5-Cy. 12 $\frac{5}{8}$ " - 15 $\frac{3}{4}$ "

If Boilers fitted with forced draught

No boilers

Tail Shaft. If fitted with a continuous liner

No

If fitted with an outside gland of

Yes

approved type

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *+LMC 10.35*

It is noted that an additional generating set will be fitted at a later date and that an inclusion fee has been charged.



31/10/35
 © 2021

Lloyd's Register
 Foundation