

COPY

Ship's name "SEIYUN"

Port

ADD.

No. 3536

Class is subject to

Last survey date 11.6.63.

764  
wasted bottom plating in M.R., side and bottom plating in transom space, side plating and frames in F.P. tank, aft main deck plating and bilge strake in way of No.1 hold (s.s.f) being specially examined and dealt with as necessary by the Special Survey.

S.R.L. Appendix (as before or none)xxx

Surveys due

SPECIAL SURVEY (C) due 9.62. Postponement until 9.63 approved 7.3.63.

Nature of present survey (afloat and in drydock)

S.R.L.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS.

SS proposed to be completed by

Recommendation

SUBMITTED record of DS 6,63 be assigned, subject as above, but ACTION continue to be DEFERRED for Special Survey, by 9,63.

DS 6,63 Subject.

IN S.R.L. APPENDIX.

Indents in shell plating (p & s).

ABM.  
9.7.63



© 2021

Lloyd's Register  
Foundation

011869-011870-0162