

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

Your Ref: SE:FAS/ID

8th May, 1964

^C
RLT/RW

Dear Sirs,

m.s. "NORDIC"

When this ship was at Sydney in March last, the Surveyor reported that the port main engine aft scavenge crank web was found cracked between bolt holes.

Repairs were effected and it was recommended that this item be examined before the ship leaves the Australian Coast this voyage and be dealt with as necessary on the ship's return to the U.K.

As no information has been received that this matter has been attended to, and in view of the fact that according to the Shipping Papers the ship has left Australia, I shall be glad to learn what the position is regarding this condition of class.

Yours faithfully,

Deputy Clerk to the
Classification Committee

Messrs. Furness, Withy & Co. Ltd.,
Furness House,
Leadenhall Street,
LONDON E.C.3

Lloyd's Register
Foundation