

Ship's name "NORDIC"

Port MEL.

No. 19855

Last survey date 1.10.62.

Class is subject to shell plate A.17 (p.s) being specially examined and dealt with as necessary by the Special Survey, and to set in sheerstrake plating et. between frs.30/40 (s.s) being specially examined and dealt with as necessary by 9.62, and to sheerstrake and structure in way between frs.135/143 (s.s) being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (as before ~~XXXXXXXXXX~~)

Nature of present survey (afloat ~~XXXXXXXXXXXX~~ck)

Examination of sheerstrake plating etc.,
between frs.30/40 (s.s) as above but
negligible damage found.

Recommendation SUBJECT to shell plate A.17 (p.s) being specially examined and dealt with as necessary by the Special Survey and to sheerstrake and structure in way between frs.135/143 (s.s) being specially examined and dealt with as necessary at the next drydocking, without other conditions.

As Now Subject
without.

IN S.R.L. APPENDIX.

~~Pop~~ sheerstrake plating and
shell plating (s.s) indented.



© 2021

Lloyd's Register
Foundation

011988-011994-0105