

COPY

LLOYD'S REGISTER OF SHIPPING



Port GLASGOW

13th August, 1962

This is to Certify that I have

part
Surveyed the Machinery of the M.V. "WODIG", 9485 tons gross

of London whilst afloat and in drydock at Glasgow on the
1st August, 1962 and subsequently
and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will Recommend that in the case of this Vessel the following

Survey Records be made in the Supplement to the Register Book
DBS 8,62 when the safety valves of the Upper (Clarkson) exhaust
gas boiler have been adjusted under steam and CO (with date)
when the survey has been completed
and that her Machinery Classification Record be continued in the Book.

Subject to starboard main engine No. 4 unit top guide Metalslock
repairs being specially examined by 7,63 (2 year limit) and to
all "A" frames in port and starboard main engines being specially
examined and dealt with as necessary by 2,03 (12 month limit)
with without condition regarding port main engine No.2 cylinder
jacket and starboard side ballast low injection
valve ice clearing connection.

Parts now examined:

(C.S. Items only)

Port ME No. 4 centre guide
No. 2 and No. 3 centre crankpins and bearings.
Nos.1,3,6 and 7 intermediate shaft bearings.
All main engine driven H.P. fuel pumps.

Starb'd ME No. 3 centre connecting rod, top end and guide.
No. 3 centre crankpin and bearing.
No. 4 and No. 6 journals and bearings.

Auxiliaries Starboard main lub. oil pump.

E.H. Barth
Engineer Surveyor to Lloyd's Register

(E.H. BARTH)

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,5,60 (MADE AND PRINTED IN ENGLAND)

© 2021

Lloyd's Register
Foundation

011988-011994-0133