




Lloyd's Register of Shipping

P.O.Box 20, Opp. Railway Institute,
Vasco da Gama, Goa,
INDIA.

Reference
A/LL/43-65



Dated: 9.8.65

Dear Sir,

'EVER HAPPINESS'


generally With reference to your Classing Letter of 8.8.65, I have to advise you that the steam pipes of the above vessel were generally examined and found in order. The pumping arrangements were examined (including pipes) as far as possible but since the engine room bilges and the tunnel well, were maintained in a fairly dry condition these sections were not specially flooded for the purpose of testing.

The vessel at the time of the general examination was already partly loaded and since facilities for megger testing are not freely available, these tests were not undertaken.

Yours faithfully,

Modur
The Surveyor

The Secretary,
Lloyd's Register of Shipping,
LONDON.



Lloyd's Register
Foundation

011995.012002-0055

LR.
REPORTS

CRD

9/11
13 AUG 1965

Lloyd's Register of Shipping



© 2020

Lloyd's Register
Foundation