

Printed x  
Supp. 7.

Received London  
-8 JAN 1965

Ship's Name SS/MS "EVER HAPPINESS"  
(ex "EVER FORTUNE") Gross tons 6,766

Is there a rpt. 9? No Port Taipei Rpt. No. 64167

No. of visits 3 First date 12-10-64 Last date 21-10-64

Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) TP 64163

Date of completing rpt. 12-12-64 Surveyed at, if different from Port above Keelung

Surveyed afloat and/or in D.D. Afloat Last date of examination in D.D. -

Has a Load Line Survey been held? No Freeboard Marks verified Yes

State which additional Rpt. 8 is attached: (Com), (PS), (DR), (EQ), (Rig)

Survey fees Damage fee Expenses US \$ 30.-

Owners Alterations US \$ 140.-

(75% of fee credited to surveyor concerned.)

S.A. fee 12 JAN 1965

I have surveyed the above ship in accordance with the Rules for Freeboard verification and conversion of Nos. 2A & 3 Holds & tween deck hatchway (Owner's Alterations).

Note :- Vessel changed to Chinese Registry. New Owners "First Steamship Company Ltd., 42, Hsu Chang Street, Taipei.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

Conversion (Owners' Alterations) :

The Nos. 2A & 3 holds have now been converted into one hold by the renewal of the bulkhead at Fr.96.

The existing hatchway to Nos. 2A & 3 holds have now been combined and made into one hatchway at the tween deck.

Please see Drawing "Conversion of No.3 Tween Deck Hatches" and "Capacity Plan" now attached.

(London cable dated 19th June, 1964 copy attached).

I recommend that this ship remain as classed with/without fresh record of dry docking subject to any outstanding conditions of class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate. Acting Surveyor to Lloyd's Register of Shipping

Date of Committee MONDAY 18 JAN 1965

Minute

Deferred for comp SS (by 6.65)

Write Taipei - check.

|  |
|--|
| ALSO FOR                               |
| SPL FOR                                |
| RECORDED BY<br>TRC<br>RECORDS<br>DEPT. |
| SRL                                    |
| POSTING                                |
| HEADER                                 |
| CERT.                                  |

H.S.M. Tan  
Acting Surveyor to Lloyd's Register of Shipping

Lloyd's Register Foundation

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due