

2- MAY 1962

Received from Chief Ship Surveyor.....

SHIP'S NAME "LEONIDAS CAMBANIS" REPORT ROT. No. 53584
EA

Standing Conditions of Class: SUBJECT to 15 fathoms of chain cable being supplied at the earliest opportunity and to bulkhead plating and fastenings in way of main condenser overboard discharge being examined and dealt with as necessary next drydocking.

R.L. Appendix. (As before ~~or None~~)

Condition of Present Survey: (Afloat ~~and in dry dock~~)

Supply and verification of 15 fathoms of chain cable as above.


Recommendation: SUBJECT to bulkhead plating and fastenings in way of main condenser overboard discharge being examined and dealt with as necessary next drydocking, without other conditions.

As Now Subject
Without.

IN S.R.L. APPENDIX.

Minor indents in shell plates A.6 (s.s) and A.8 (p.s) from aft and in 'F', 'G', & 'H' side shell strakes (p & s).

Indented sideshell plates (p.s).



© 2020

Lloyd's Register
Foundation

011995-012002-0145