

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

19th March, 1962.

Dear Sirs,

'C'
AEG/CAG

Steamer "LEONIDAS CAMBANIS."

At a survey held by the Society's Surveyors at Vancouver in December/January the windlass port inboard bearing pedestal was found fractured.

Temporary repairs were effected and it was recommended that the windlass port inboard bearing pedestal be specially examined and dealt with as necessary before the end of December 1962.

The Committee have continued the class subject, inter alia, to this matter receiving attention by that time.

Yours faithfully,

pro Clerk to the
Classification Committee.

Messrs. S.G.Embiricos Ltd.,
Dunster House,
Mincing Lane,
LONDON, E.C.3.



© 2020

Lloyd's Register
Foundation

011995-012002-0150