

Received from Chief Ship Surveyor... 13 MAR 1962

SHIP'S NAME "LEONIDAS CAMBANIS" REPORT VCR No. 11391

EA

standing Conditions of Class:

SUBJECT to 15 fathoms of chain cable being supplied at the earliest opportunity. 9

L. Appendix. (As before or None)

ure of Present Survey: (Afloat and in dry dock)

Docking:- Damage repairs - stevedore.  
Wear and tear repairs.

mmendation:

SUBMITTED record of DS 12,61 be assigned, subject to as above and to bulkhead plating and fastenings in way of main condenser overboard discharge being examined and dealt with as necessary next drydocking.

DS 12,61 Subject.

IN S.R.L. APPENDIX.

Minor indents in shell plates A.6 (s.s) & A.8 (p.s) from aft and in 'F', 'G' & 'H' side shell strakes (p & s).

Indented side shell plates (p.s).

ENGINEER SURVEYORS TO NOTE.

© 2020  
9-3-62.

Lloyd's Register  
Foundation

011995-07002-0151