

achinery  
will it

REPAIRS, OR EXAMINATION AS PER RULE, FOR DRY DOCKING. Shell plating, rudder and sternframe e

4 DEC 1954

Received from Chief Ship Surveyor

SHIP'S NAME "LADY ISOBEL" REPORT Syd. No. 27708  
JD.

Outstanding Conditions of Class: Subject to the A.P. tank top  
being further examined at the next drydocking.

Endorsement of Class (B) (AS before ~~EXXNEE~~)

Nature of Present Survey: (Afloat and in dry dock)

Docking.  
Repairs to after peak tank top as above.

Recommendation:

SUBMITTED record of docking 11,54  
be assigned, without special condition,  
but with Endorsement (B).

11,54 Syd. Without.

~~ENDORSEMENT OF CLASS (B).  
Bulwark plating (s.s.)  
abreast No.2 hatchway set in.~~



© 2021 *SPR*  
9-12-54

Lloyd's Register  
Foundation

012019-012026-0140

upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as  
of survey, 1,33," or "to remain as classed and to have record of survey, 1,33, and the notations of ss No. 1-33."

the  
ng  
Lis  
he  
our  
or Y.M.  
e if o  
ed: M  
ards,  
n, how  
e if w  
nt lett  
No. of  
State  
lght  
(on  
ile len  
oker  
& War  
and B  
in the