

"FJELD"

Osl. 5664
Bgn. 2990
Osl. 5746
" 5802
Cff. 55333

Reports of surveys held between 7.41 and 8.44 have now been forwarded by the Norwegian Surveyors.

In 7.41 at OSLO a BS was partly held, four furnaces being faired.

In 10.42 at BERGEN the Special Survey No.3 was partly held and the BS also held. On account of damage through grounding the screw shaft was examined and on account of fire damage most of the electrical equipment on deck was renewed.

In 3.43 grounding damage was reported, the machinery spaces being flooded. Two furnaces were found to have collapsed.

In 8.44 at OSLO a complete Special Survey was held, the Screw shaft examined and propeller renewed. On account of the above damage, the insulation of the cylinders and boilers was renewed, one furnace renewed and one partly renewed. The Oslo Surveyors recommended a record of ELMC 8.44 and S (CL) 4.44.

At a Survey now held by the CARDIFF Surveyors they report the main circulating pump being reconditioned.

In accordance with the Committee's decision of 9th August 1945 regarding vessels owned in countries formerly occupied by the Germans, it is submitted the vessel's class be reinstated in the Register Book with fresh record of ELMC 8.44
S (CL) 4.44.

Reinstate particulars in R.B.



© 2021
23.8.45.

Lloyd's Register
Foundation

012096-012101-0065