

Rpt. 8.

(Received at London Office)

No. 54762

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 16 MAR 1948 19... Port of HULL

No. in Survey held at HULL. Date, First Survey 20-2-48 Last Survey 2-3-1948

12671 on the Wood, Iron or Steel M.V. "RIVER TRENT"

TONNAGE: - Built at Goole By whom Goole S.B. & R.Co. Ltd. When 1935

GROSS 246 Owners R.H. Hunt. Owners' Address -

UNDER DK. 173 Managers - Port belonging to Hull

NET 116 Surveyed Afloat or in Dry Dock? Dry dock Name of Dock Brown's Dry Dock. Destined Voyage -

Cell D Bor D Ba feet; uE & B feet; f feet } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 51236 Port Hull

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage Repairs.

- Damage (1) Stated caused by grounding in River Wene on 12th January, 1948.
- (2) Stated caused by being struck by unknown vessel on 20th February, 1948 whilst lying at Old Forge Wharf, Hull.
- (3) Stated caused by being struck by unknown vessel on 26/27th February, 1948 whilst lying at Old Forge Wharf, Hull.

Repairs:- The following repairs were agreed upon:

Damage (1) Shell plate remove, fair & refit - (S.S.) B.5.
 Shell plates fair in place - (S.S.) B.4, B.6; C.3, C.4.
 Bilge keel P. & S. - 2 lengths remove, fair & refit.
 Shell tee-bar fair in place. P.T.O.

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faired or Repaired								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE		Bulkheads		Engine Room Skylights		Copper, or Y.M.	
Decks	Caulking of Decks	Ceiling	Cement or Asphalt	Coal Bunkers, Openings, Covers, &c.	Oil Bunkers	When fitted, Month	Year
Coamings	Beams & Fastenings	Rudder	Steering gear and its connections	Scuppers	Cargo Hatchways	Boats	Masts, Yards, &c.
Outside Plating	" " in way of sidelights	Windlass	Have pumps been examined and found efficient?	Hatches	Hatches	Condition, how ascertained	(State if wedges removed.)
Frames	Reverse Frames	Have Sluice Valves been examined and found efficient?	Have Watertight Doors been examined and found efficient?	Planking	Caulking	Equipment letter	Equipment letter
Longitudinals	Transverses	Have Ventilators and their Coamings been examined and found efficient?	Air and Sounding Pipes	Treenails	Breasthooks & Stemon	Transoms, Pointers & Crufoes	Timbers of Frame at openings
Floors	Keelsons	Have the Tanks been examined internally?	Have the Tanks been tested?	Stringers, Clamps & Shelves	Salting	State if examined.	Stringers, Clamps & Shelves
Stringers	Inner Bottom Plating	Doubling Plates under Sounding Pipes					

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

For the information of the Committee.

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	3	3	16 MAR 1948
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19
Committee's Minute	See minute of 12.3.48			
Character Assigned	See minute of 12.3.48 on Hull 54236			

J. Bessley. © 2021
 Surveyor to Lloyd's Register of Shipping.
 General Committee
 Thursday, 8th April, 1948
 Glasgow Committee decision confirmed

012096-012101-0126

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

MADE AND PRINTED IN ENGLAND. (The Surveyors are requested not to write on or below the space for Committee's Minutes.)

As Certificate required? If so, to be sent to

