

LLOYD'S REGISTER OF SHIPPING

Port.....PORT KIRKDate.....19th November 1965

This is to Certify *that I have surveyed part of the machinery*
of the S.S. "MAESS VENTURER" *gross tons* 25 691
for advancement of continuous survey of machinery whilst the vessel lay afloat
at this port on 16th November 1965 and subsequently

and that all my recommendations have been carried out to my satisfaction. I
am reporting accordingly and recommending to the Committee of Lloyd's Register
of Shipping that the machinery classification should be retained and the following
survey records assigned

C.S.M. (with date) on completion of survey, subject
to port turbo alternator being examined under working conditions before the
end of February 1966. Also subject to all other conditions at present attached
to the vessel's class being dealt with as previously recommended.

Parts now examined:—

- Main reduction gear. (Through inspection doors).
- Main thrust block, shaft and bearings.
- General service pump.
- Starboard main extractor pump.
- Forward and after feed pumps for steam generator.
- Pumping arrangements.
- Remaining items of electrical equipment.
- Holding down bolts and checks.
- Main condenser.
- Engine tested working and manoeuvring

James S. Book
 Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
 CSM Continuous Survey of Machinery
 DBS Donkey Boiler Survey
 ES Engine Special Survey

MBS Main Boiler Survey
 OF Fitted for oil fuel (date) FP above 150° F.
 SGS Steam Generator Survey
 SPS Steampipe Survey

TS Tailshaft Survey
 TS(CL) Tailshaft Survey—Continuous Liner
 TSN Tailshaft renewed
 TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or of its Surveyors, or other Officers, Servants or Agents of the Society."