



Lloyd's Register of Shipping

48 DALHOUSIE STREET,

QUEBEC. September 27th.1945

Mr. N. Dobson
Principal Surveyor in Canada
LLOYD'S REGISTER OF SHIPPING
231 St. James St. West
MONTREAL, P.Q.



"ROCKLAND PARK"&"HAMILTON PARK"
Montreal Report Nos. 6591/6592

Dear Sir:-

In reply to your letter of the
25th. inst. regarding extracts from a Classing
Letter received from Wokingham regarding the above,
the following information is forwarded:-

"The thickness of the 10"X3 $\frac{1}{2}$ "bulb angle
bulkhead stiffeners in each Vessel is
.52" ✓
The thickness of the bottom strake of
plating of the after peak bulkhead is
7/16" as in the "Willow Park". ✓
The length of the forecastle in accor-
dance with Circular 1551 is 33'-8". ✓
The thickness of the Upper deck plating
within the line of opening in each case
is 5/16-3/8". ✓

Attention will be given, in future
Reports regarding the last paragraph of your letter.

The inaccuracies of these parti-
culars are regretted.

Yours very truly,

© 2021
Lloyd's Register
Foundation
SURVEYOR.

RAH/KM.

1.c.8

#

LR¹
-2

12 OCT 1945



© 2021

Lloyd's Register
Foundation