

COPY.

ENCLOSURE.

14th April, 1917.

Dear Mr. Warlow,

I return Glasgow First Entry Report No. 36755 and shall be much obliged if you will get the Surveyor to state thereon whether the dry tank in way of the Boilers is watertight, and if it has been tested as required by the Rules.

It is concluded that the spacing of 36" given for the forecastle beams is a clerical error, also that the foremast is increased in thickness or is double in way of the partners, and the Surveyor should make these points clear.

With kindest regards,

Yours faithfully,

P.L. Warlow, Esq.,
GLASGOW.



© 2021

Lloyd's Register
Foundation

012148-012158-0135