

"SANTO"

Oslo. 6735

Before this case receives consideration, IT IS SUBMITTED the Oslo Surveyors be asked for their comments on the following:-

- 1) It is noted an approved type of oil gland is stated to be fitted to the screwshaft, although no mention of ~~this~~ was made on the shafting plans. Please forward particulars of same.
- 2) A revised plan of the electrical installation does not appear to have been submitted for consideration, as requested in Secretary's letter of 11. 11. 50.
- 3) The correct MN appears to be 173, whereas the reported figure of 155 is the old N.H.P.

Em

22. 3. 51.

see. Cliph
Blubb

Cl. to Oslo: - 3073



© 2021

Lloyd's Register
Foundation

012246 - 012255 - 0054