

DAWNLIGHT

Submitted the Greenock Surveyors
be advised that their Report C11 has
been examined and found in order.

It is concluded that freeboards
have been assigned by the Board of Trade
and the Surveyors verification of marking
form is duly awarded.

It would also appear that the
marking form for the sister ship RAYLIGHT
has not been received yet.



© 2021
Lloyd's Register
Foundation
16.8.65
19/8/65

012246-012255-0252