

4E

is subject to

the propeller being specially examined and dealt with as found necessary at the next dry docking.

'2- APR 1962

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME.....

"BAYON".....

REPORT.....

H.Kg.....

No. 16854.....

Docking.

MBS due 11.61 - now held.

Some repairs effected to main boilers.

IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh record of MBS 2.62 now, without special condition

  
30.3.62

It is concluded that the condition of the propeller was found sufficiently good for the Surveyors to delete the subject item, but this should be confirmed.

© 2021



Lloyd's Register  
Foundation

012365-012369-0185