

Received from Chief Ship Surveyor..... 11.0 AUG 1962

SHIP NAME "SOUTHERN CLIPPER" REPORT ROT. No. 54211

EA

Standing Conditions of Class:

SUBJECT to forecastle sheerstrake plates Nos.7 & 8 also main sheerstrake Nos.6 & 7 (s.s.from forward) being specially examined and dealt with as necessary on arrival at Rotterdam to which port she is now proceeding.

L. Appendix. (As before ~~XXXXXX~~ or None)Area of Present Survey: (Afloat ~~and in dry dock~~)

Permanent repairs to damage caused by contact including the conditions of class.  
Deferred repairs to damage caused by contact with a dolphin.

Recommendation:

SUBJECT to indented shell plates G.3, H.3 & 4 in way of dry cargo hold and deep tank (p.s.f) being dealt with as necessary at the next drydocking, without other conditions.

SUBJECT  
WITHOUT.

IN S.R.L. APPENDIX.  
(Main structure partly  
of P.403 and KNT Steel).



© 2021

31.7.62

Lloyd's Register  
Foundation