

Received from Chief Ship Surveyor

12 JAN 1960

SHIP NAME "STECKENPFERD" REPORT Ist. No. 4863

standing Conditions of Class: NONE.

L. Appendix. (As before ~~or None~~)

re of Present Survey: (Afloat ~~and in dry dock~~)

Temporary repairs to holed stem plating on account of ice damage.

Recommendation:

SUBJECT to holed stem and bow plating being specially examined and dealt with as necessary on arrival at Wismar at end of present voyage.

As Now. Subject

IN S.R.L. APPENDIX.
G.4 (s.s.f) indented.



© 2021
4.1
21/1/60

Lloyd's Register
Foundation