

FOR CONSIDERATION BY THE COMMITTEE OF LLOYD'S REGISTER OF SHIPPING

Ship's Name ~~SS~~MS "Denman". LR.508869.

20 JUN 1966

Gross tons 2, 265. Port of Registry Newcastle, N.S.W. Port Sydney, N.S.W.

Date of build 6/1949. Is there a rpt. 8? Yes. Rpt. No. 38680

No. of visits Two (2). First date 26th May, 1966. Last date 27th May, 1966.

Interim Cert. issued & copy herewith? Yes. Damage rpt. issued & copy herewith? No. Last rpt. (H.Q. only)

Date of completing rpt. 8th June, 1966. Surveyed at, if different from Port above

Is a rpt. 9A attached? No. MN 252. Nature of survey Docking Survey.

Survey fees Damage fee Expenses

See Report 8.

S.A. fee

DOCKING

Propeller Good. Sea connections Oil gland

Wear down of stern bush

Fastenings Good. (if relined, state clearance before and after)

Has screw shaft been drawn? No. 0.125".

Has shaft been changed? No. Date of examn. 27th May, 1966.

Has shaft now fitted been previously used?

Has shaft now examined/fitted a continuous liner? Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG) MAIN

Air heaters

Superheaters

Safety valves

Mountings, doors and fastenings

Safety valves adjusted to Sat Spt

Boiler securing arrangements

Exhaust gas heated economisers and their safety valves

Main economisers

Steam heated steam generators

Steam generator safety valves adjusted to

Forced circulating pumps

Funnel

Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules? Were oil burning system & remote controls examined in accordance with rules?

I recommend that the machinery of this ship remain as classed with/xxxxxx fresh record of Docking Survey 5/66 now, subject to any outstanding conditions of class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

MONDAY 11 JUL 1966

As now

012591-012591-0101

ALSO FOR

SPL FOR

NOTED BY CESR

POSTING


HEADER

CERT

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

been effected or it is considered that re-examination or repairs should be made before that date a distinguishing mark must be inscribed against the item and the circumstances and action taken or recommended described

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have



EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN
AUXILIARY
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?


ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY	
Total kW or kVA		Total kW or kVA	
a	Generators	l	Generators & governors
b	Exciters		
c	Air coolers	m	Motors
d	Motors		
e	Air coolers	n	Switchboards & fittings
f	Control gear cables, etc.	o	Circuit breakers
g	Insulation resistance	p	Cables
h	Insulating oil test	q	Insulation resistance
i	Overspeed governors	r	Steering gear generators & motors
j	Magnetic couplings	s	Navigation light indicators
k	Air gap		

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

N I L.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.



© 2021

Foundation