

TELEGRAMS: REGISTER, KOBE.
TELEPHONE: FUKIAI ③ 0142, 2508



Lloyd's Register of Shipping.

(UNITED WITH THE BRITISH CORPORATION REGISTER)

(P. O. Box No. 446)

83, KYO-MACHI,
IKUTA-KU

RECEIVED

28 MAY 1952

Kobe, 15th May, 1952.

Reference

"OLINDA"

Dear Sir,

With reference to your letter of the 17th April, 1952 regarding the recommendation by the Karachi Surveyors for permanent repairs to the Starb'd Side indented shell, we have to state we were not aware of their recommendation at the time of survey in Kobe in January. The damage was specially examined and it has been recommended that permanent repairs be effected at the next drydocking. (See Kobe Report.)

Yours faithfully,

L. Burns

For the Surveyors.

The Secretary,
LONDON.

M 5, 52. KOBE



© 2021

Lloyd's Register
Foundation

012620-012623-0148

Surveyor to Lloyd's Register

Travelling Expenses (if charged) £

Second Surveyor's Fee (if any) £

Committee's Minute

TUES. 24 JUN 1952

1250. Transfer
Surveyors are required

CLASSIFICATION

Re

H

FOR THE SIGNATURE

FOR THE SIGNATURE

(..4700)

ment letters be attached to the next communication. (See note
specifically examined and it has been recommended that letters
at the time of arrival in Korea in January. The damage was
to have to state we have not aware of the recommendation
for replacement referring to the letter of the 19th January 1951.
1951 regarding the recommendation by the Korean authorities
with reference to your letter of the 19th April.

Dear Sir:

RECEIVED

RECEIVED

RECEIVED

© 2021

Lloyd's Register
Foundation



Reference

TELEGRAM
TELEPHONE

