

in parallel No, are shunt field regulators provided Yes Is the compound winding connected to the negative
negative Have machines over 100 kw. been inspected by the Surveyors during manufacture and testing — H
test for machines under 100 kw. been supplied and the results found as per Rule

"OLINDA"

(Wm. Denny & Bros. Ltd. Yard No. 1432)


The electrical equipment of this vessel has been installed under special survey, tried under full working conditions and found satisfactory.

The materials and workmanship are good.

Last date of survey 21st February, 1950.

W. Haffner

20th March, 1950.



© 2021

Lloyd's Register
Foundation

012620-012623-0163

make of fuses "Artis", are all fuses labelled Yes If circuit breakers are provided for the gener
overload do they operate 50% and at what current do the reversed current protective devices operate
point Boxes, Section Boards and Distribution Boards, is the construction as per Rule