

Class is subject to

4E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor..... 21 AUG 1962

SHIP'S NAME

LENGKENG

REPORT

D J A.

No. 6029


ES+1 advanced.

The Surveyor reports the crankshaft of the Starboard
aux. diesel engine was found fractured across
 the forward web, time and cause not stated.
He recommends the crankshaft be renewed by end
of November 1962 (4 mos limit)

It is submitted that this
 vessel is eligible to remain
 as **CLASSED**.

Subject as recommended

X



© 2021

 Lloyd's Register
 Foundation

21/8/62

012705-012710-0056