

9 - APR 1964

Ship's name

"LANTAO"

Port

Ist

No. 5484

Last survey date 13.3.64.

GB Class is subject to

bottom shell plates B.2 and C.1
(p.s.f) being specially examined and dealt with as necessary
also to shell plating in 2nd strake below sheerstrake
in way of No.5 hold (s.s) being permanently repaired,
next drydocking.

S.R.L. Appendix (as before ~~xxxxxxx~~)

Nature of present survey (afloat ~~and in drydock~~)

Examination afloat after grounding.

Recommendation

SUBJECT as above, but further ACTION be
DEFERRED for examination in dry dock after
grounding.


SUBJECT

INSERT IN ~~S.R.L.~~
Drydocking (grounding).

IN ~~S.R.L. APPENDIX.~~

Indented shell plating (s.s.f)
also shell plates C.3 & D.6 (p.s.f)

C.S.S. Records Dept.
to note.



© 2021

Lloyd's Register
Foundation