

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

28th October, 1964.

C.
DHGK/DET

Dear Sirs,

CLASSING LETTER

40325 "MARLY I". As recommended. As the screwshaft now complies with the Rules for four yearly surveys, you may inform the Owners that it will be in order for future surveys to be held at intervals of four years, the next survey becoming due in September 1968.

You should also inform the Owners that if at any docking intermediate between Screwshaft Surveys the wear-down of the sternbush is, in the opinion of the Society's Surveyor, excessive, the shaft will require to be drawn and the bush relined.

It should be added that no period in excess of four years will be allowed between Screwshaft Surveys beyond what is reasonable to enable the ship to reach a port where the survey can be held.

Yours faithfully,

pro Clerk to the
Classification Committee

The Surveyors,
ANTWERP.



© 2021

Lloyd's Register
Foundation

012722-012727-0149