

27 OCT 1964

Ship's name "MARLY 1" Port Ant No. 40325
Last survey date 8.9.64.

GB Class is subject to NONE

ACTION is DEFERRED for examination in dry dock
after grounding.

S.R.L. Appendix (as before or none) ~~XXXXXXXXXX~~

Nature of present survey (refloat and in drydock) ~~XXXXXXXXXX~~

Docking: Examination on account of grounding and damage
(cause unknown).

Recommendation

SUBMITTED record of 'DS 9,64' be assigned,
subject to indented keel plates Nos.2 & 3 forward
A.3,4 & 5 (p & s.f) and set in shell plates
F.5 & 6, G.5 (s.s.f) being specially examined
and dealt with as necessary next drydocking.

DS 9,64 Subject

~~DELETE FROM S.R.L.
Drydocking (grounding).~~

~~IN S.R.L. APPENDIX.
(Main structure partly of P.403 & XNT Steel)
Shell plate No.2 in poop sheer etc. (p.s) slightly indented.~~



© 2021

Lloyd's Register
Foundation

Handwritten signature and date: 12/10/64