

9- MAY 1963

EA

<u>Ship's name</u>	"PADEREWSKI"	<u>Port</u>	BBO	<u>No.</u>	13463
				<u>Last survey date</u>	22.3.63

Class is subject to

15 fathoms of chain cable being supplied at the earliest opportunity.

S.R.L. Appendix (as before ~~XXXXXX~~)

Nature of present survey (afloat and ~~in drydock~~)

Conversion from C.S.D. to O.S.D.
Ice damage - temporary repairs.

Recommendation

SUBJECT as above and to defective side shell rivets in lower strakes in way of after end of No.2 hold (s.s' being specially examined and dealt with as necessary next drydocking).

As Now Subject.

~~IN S.R.L. APPENDIX
(Main structure partly of P.5 Steel).~~

C.S.S. Records Dept.
to note.



QSP 2021

23/4/63

Lloyd's Register
Foundation

012796-012800-0123