

19 OCT 1962

Ship's name "PADEREWSKI"

Port GDK

No. 1060

Last survey date 2.10.62

Class is subject to

NONE

S.R.L. Appendix (as before ~~XXXXXXXXXX~~ or none)

Nature of present survey (afloat ~~XXXXXXXXXX~~ dock)

Temporary repairs to E.R. sea chest, (p.s).
Equipment: Damaged length of chain cable disconnected.

Recommendation

SUBJECT to 15 fathoms of chain cable being supplied at the earliest opportunity and to permanent repairs to E.R. sea chest in No.6 D.B. tank (p.s) being permanent repaired next drydocking.

As Now Subject.

IN S.R.L. APPENDIX.

(Main structure partly of P.5 Steel).

S.P.K.
18/10/62.

End. S.1



© 2021

Lloyd's Register
Foundation

012796-012800-0135