

COPY

Met House
772C

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

Enclosures:

6th December, 1960.

Classn. (S)

Dear Sirs,

DHGK/AB

Motorship "BLANDFORD"

Reverting to previous correspondence in this case the reports of surveys held at Amsterdam between 30th September and 27th October have now received the consideration of the Committee and a record of Drydocking 10.60 and the notations Special Survey 10.60 (Adv), Continuous Survey 10.60, Screwshaft Examined, Auxiliary Boiler Survey and Steam Pipe Survey all with date of 10.60 have been assigned. I have the pleasure to enclose the official Classification Certificates in respect of both hull and machinery.

Some Metalock repairs were carried out to the LP cylinder of the outboard steam generator engine, but it was recommended that this LP cylinder should be specially examined or renewed by the end of April, 1961. The Committee have continued the class subject to this matter being dealt with by the time stated.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

The Blandford Shipping Co. Ltd.,
33-34, Bury Street,
LONDON, E.C.3.



© 2021

Lloyd's Register
Foundation

012836-012844-0270