

COPY.

# LLOYD'S REGISTER OF SHIPPING

Port Baltimore, Maryland

June 24, 1959

This is to Certify that I have

surveyed the Machinery of the M.V. "HEDDA DAN", 5188 tons gross of Esbjerg,  
moored in drydock and afloat at the plant of the Bethlehem Steel Company,  
Highway, Baltimore, Md. on the 10th June, 1959 and subsequently for Classi-  
fication Survey,

and that I will transmit to the Committee of Lloyd's Register of  
Shipping, London, a Report stating that all recommendations made by  
me in connection therewith have been carried out to my satisfaction; also

that I will **Recommend** that in the case of this Vessel the following  
Survey Records be made in the Supplement to the Register Book  
ME 6.59, SPS 6.59 and DBS 6.59 on completion

and that her Machinery Classification Record be <sup>entered</sup> ~~continued~~ in the Book.

subject to the oil fired boiler being re-tubed by September 1959 (3 mos. limit),  
boilers examined under steam and their safety valves adjusted under steam.

Parts now examined:

(C.S. Items only)

A.V. Riise-Madsen

Engineer Surveyor to Lloyd's Register.

## KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TBN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150° F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, fault or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."