

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES


Ship's Name HEDDA DANOfficial No. —Port of Registry ESBJERGThis ship has been under survey at BALTIMOREon 22-28 Nov 1960 ~~195~~ and the following alterations to the conditions of assignment of loadlines have now been effected ~~to~~ as follows:-

"All tween-deck trimming hatches, a total of 18, fitted with a bolted-on steel plate, bolted down with 3/4" bolts, spaced 5" apart, watertight packing and keep chain fitted to each cover. The existing 3" coaming retained and a wood plug fitted over each of the new steel covers. On completion, all the new covers satisfactorily proven watertight."

Extract from Rpt 8, Baltimore, N°12005-5th Dec 1960

A.R. 18.5.61

A copy of this Report has been placed on board.



© 2021

Lloyd's Register
Foundation

012925-012632-0130