

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

BY AIR MAIL

ship

21st September, 1962.

Dear Sir,

Coastal Patrol Launches for the
Government of Burma built by Messrs.
Kanawa Mfg. Ltd. Yard No.K.129, 130
and 131.

I duly received your letter of the 11th September,
regarding the defects as found on the above vessels
arrival at your port.

With regard to the three points raised, I have to
state that:-

commissioning

1. It is agreed that the launches can be accepted
for class provided the Owners are agreeable, but the
classification certificate would probably be made
conditional or subject to repairs being carried out prior to
and, should the Owners desire a classification certificate
without conditions attached, then the recommended repairs
should be carried out under your supervision and duly
notified to this Office on a Report 8.

2. The question of trim is not a matter for classifi-
cation but on the understanding that ballast is well
distributed no stiffening will be required. Solid
ballast should be bedded in a suitable composition and
secured in place.

3. Regarding the Owners' proposed alterations to the
forward fuel tank, I have to state that these would
appear to be in order, provided the new oil fuel tanks
are constructed in accordance with the Society's Rules



© 2021

Lloyd's Register
Foundation

012925-012932-0205 1/2

- 2 -

and to the Surveyor's satisfaction. A plan showing the proposed modifications to the piping arrangements should be submitted for approval as soon as possible.

Yours faithfully,

c.c. Eng.

pro Secretary.

L. H. Todd, Esq.,
RANGOON.

HDR/MM

c.c. Todd.



© 2021

Lloyd's Register
Foundation

0205 2/2