

F.E.

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME St S "PORT WAIKATO" Rpt. RM No. 17703

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

P. Long  
Transverse No. 2385Depth "d" 10.42Framing: Table No. 1Description Built angle frames as approved2<sup>nd</sup> Longitudinal No. 7560Proportions  $\frac{\text{Length}}{\text{Depth}} = \frac{13.58}{}$ Deck Sheerstrake as approvedRevised Lulls

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A. I. (Steel)

1 D<sup>+</sup> (Stl) Well D<sup>+</sup>

Cell D.B. 114 195 t, F.P.T. 80t, A.P.T. 28t

F.K., 3 B.H., pt cem pt asp. Glydo A CP.

Q 105', B 11', F 24'. machy app.




The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

It is concluded the number deckhatch webs in No 2 hatch is as approved + not as reported but the surveyors should be requested to state if this is so.

013059-013062-0243

6.12.29



© 2021

Lloyd's Register Foundation