

COPY

LLOYD'S REGISTER OF SHIPPING

14 CROSS SHORE STREET, GREENOCK.

9th October, 1963.

Dear Sir,

"RAYLIGHT"

Scotts' S.B. & E. Co. Ltd., Yard No. 695

With reference to the F.E. Report No. 27341 in connection with the above ship, the certificate of the $\frac{3}{4}$ " cwt. stream anchor has been mislaid by the owners. The stream anchor certificate No. 23739 (stamped) has been placed on board but not checked against the certificate. An application has been made for a copy of the certificate to be obtained as soon as possible and upon receipt the necessary information for the F.E. report will be forwarded. I am taking this course in order that the F.E. report will not be held up any longer.

Yours faithfully,

(sgd.) James K. Young

The Secretary,
Glasgow.



© 2021

Lloyd's Register
Foundation

013224-013231-0195

