

Reg. 1a.)

(Received at London Office 13-7-56 19.....)

o. 333 Place *Warden* Date *9-7-56* 19 *56*

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to Specially Survey during Construction the Hull, Engines and boilers of the Vessel No. *552* building by Messrs. *HAARL. SCHEEPSBOUW MAATSCHAPPY* for Messrs. *FISCO DE CHILE*

1150 Tons. Length *73* - , Breadth *11.90* , Depth *7.40/5.15*
tended to be Classed *✱ 100 A.1 FINISH ICE CLASS "A"*

We undertake to arrange for every facility to be given to the Surveyors carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connection therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Sms. J. H. van der ... Engine Makers

RECEIVED Boiler Makers

H.V. Haarlamsche Scheepshouw Maatschappij

Signature *H. van der ...*

13 JUL 1956
Lloyd's Register of Shipping,
1, Fenchurch Street, London, E.C.3.

To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—

"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

Rebate of 25% 1125,--

best price for exchange: £. 3375,--

013252 - 013259 - 0122

Lloyd's Register Foundation

2nd teak ✓

Forecastle Deck.
Stringer Plate, breadth and thickness.

1200 x 6 1/2 ✓

Hatchways

thickness

SSCANT

AS IN

HTR.

Thickness.

Inches.

14 ✓

12 ✓

12 ✓

8-20 ✓

10 1/2 ✓

10 1/2 ✓

18 ✓

18 ✓

10 1/4 ✓

RTIGH

Vessel—

k (Sec. 3)

below

~~SHIP~~
ENG

ADMIN./SEC.

R.A.P.

Chief
Eng

X

STEM

forging ø 200 ✓

Rebat



© 2021

Lloyd's Register
Foundation