

29 SEP 1958

Received from Chief Ship Surveyor.....

SHIP'S NAME "BELGRAVE" REPORT Sou. No. 25063.
AR.

Outstanding Conditions of Class: Subject to indented side shell plating etc. (p & s.f) being dealt with by next Special Survey and to permanent repairs being effected to indented shell plate D.5 etc.(p.s from fwd.) at the Special Survey and to 30 fathoms of chain cable being supplied at the earliest opportunity.

Endorsement of Certificate (As before ~~xxxxxxx~~)

Surveys due: SPECIAL SURVEY (C) due 9,58. Postponement until 9,59 approved 7,58.

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Supply and verification of anchor cable (subject item).

Special Features: None.

Is Interim Certificate in order (Yes ~~No~~ ~~None~~)

Items Outstanding: (If any for S.S.) All items.

S.S. to be completed by:

Recommendation: SUBJECT to indented side shell plating etc. (p & s.f) and to permanent repairs to indented shell plate D.5 etc. (p.s. from fwd.) being effected by next Special Survey, without other conditions, ~~but further action to be taken for the~~.

Subject; amended.

S.R.L. APPENDIX.

Shell plate F.10 (s.s.f) indented.
A number of keel and bottom shell plates (p & s) and stem bar slightly buckled.

James
29/9/58



© 2021

Lloyd's Register Foundation